




*Worldwide repairs carried out with PolymerMetal®*

**REP-# 058**



Repair of an installation pipe with MM-metal UW and Hardener UW3. The leakages have been caused by corrosion due to water and sand.

**MultiMetal**  
the MetalExistenceCompany®