



*Worldwide repairs carried out with PolymerMetal®*

REP-# 126



Repair of a pump housing. Damage: erosion and corrosion had reduced the wall thickness to a minimum. The resulting damage was a hole in the housing. For deep wash-outs Ceramium, pasty with MM-Fabric mats (steel) were used. For the purpose of wear-and-tear resistance the pump was coated with Ceramium, liquid.

**MultiMetall**  
the MetalExistenceCompany®