



Worldwide repairs carried out with PolymerMetal®

REP-# 041



Sealing of a large transformer in a power station. The leakage was sealed with MM-metal oL-steelceramic and Hardener red using the direct-MM-bonding method. Then a layer of MM-metal oL-steelceramic and Hardener yellow was applied to the first layer.

MultiMetal
the MetalExistenceCompany®