



## Worldwide repairs carried out with PolymerMetal®

REP-# 072



Coating of the inner respectively outer diameter of a penstock pipe with diameter appr. 1,5 m, length appr. 900 m. Damages were caused by erosion and abrasion due to water and sand. The coating was affected with Ceramium pasty with Hardener CE.

**MultiMetal**  
the MetalExistenceCompany®